



Issuer: Lars Magnusson
Tel: +46 60 142076
Fax: + 46 60 142075
E-mail: lars.magnusson@sttemtec.com

Date	2015-03-16	Page	1 of 1
Subject	Diagnostic Trouble Code Number 4		
Affected parts	ECU PartNo: 108540, 108825 and 108890		
Condition	Diagnostic trouble code number 4 is presented as 4: Boost temp sensor. This applies both to the display and the software supplied by STT Emtec. The correct translation should be 4: Water Temp Sensor		
Solution	Use this service bulletin as a translation guide if DTC number 4 should occur.		